



PowerSure - Test Readings
Servicepoolen i Stockholm
Readings for This Test (In Jar Order)
All Tests and Readings

Servicepoolen i Stockholm

Test Setup Information

String Status

Company/Region:
Site:
Site Type: UPS
System:
System Type: 110 V system
String:
Battery Type: Tudor245387955124750 SGV
Battery Mfg Date: August 13, 2001
Device: Celltron Ultra
Performed: - - : : AM
Technician: Erik Torssell

Temperature: 27°C
Volts per Jar: 12
Posts per Jar: 2
Reference: 420
T-Comp Ref: 426
String Average: 344
Jar Warning/Failure: 70% 60%
String Warning/Failure: 70% 60%
Voltage Warnings DC: 6.30
Voltage Warnings AC: 0.00

Questionable



80%

Comments:

Loaded from Ultra card file: F:\UPSCF0.CSV

Summary:

Test entered on September 13, 2006.; 9 readings were taken.; High Jar is J5 (422); Low Jar is (162).; While the string average appears to be OK, 3 jar issues were detected; 1 warning(s) ar 2 failure(s); as failures were detected, the status of this string is questionable.

Reading Status Markers: ? = Warning ! = Failure
 * next to Jar indicates reading was user-modified

Jar	DC Volts	Mhos	Ref. Value	% of Ref. Value	Reading Status	Strap μOhms 1	Strap μOhms 2	AC Ripple Voltage	AC Ripple Current	Specific Gravity	Comments
J1	13.341	162 !	426	38	FAIL	0	0	0.000	0.000	0.000	
J2	13.479	249 !	426	58	FAIL	0	0	0.000	0.000	0.000	
J3	13.401	397	426	93	Ok	0	0	0.000	0.000	0.000	
J4	13.383	391	426	91	Ok	0	0	0.000	0.000	0.000	
J5	13.415	422	426	99	Ok	0	0	0.000	0.000	0.000	
J6	13.366	298 ?	426	69	WARN	0	0	0.000	0.000	0.000	
J7	13.421	372	426	87	Ok	0	0	0.000	0.000	0.000	
J8	13.456	416	426	97	Ok	0	0	0.000	0.000	0.000	
J9	13.456	385	426	90	Ok	0	0	0.000	0.000	0.000	



Servicepoolen i Stockholm

PowerSure - Test Readings

Servicepoolen i Stockholm
Readings for This Test (In Jar Order)
All Tests and Readings

Readings for This Test (In Jar Order)

